



TEXAS FIRST AUTO INSPECTIONS

PRE PURCHASE USED CAR
INSPECTION SERVICE

Date of Inspection: 08-21-2013

Client: Fred Warmbier

Dealership Name: TEXAS DIRECT AUTO

Dealership Address: 59 SW

Dealership Sales Rep: Moises

Make: SRX

Vin#: 584438

150 POINT INSPECTION KEY:

Overview Inspection	Rating
Exterior	Good
Glass	Good
Mirrors	Good
Tires & Wheels	Good
Under Hood	Good
Suspension	Good
Electrical System	Good
Brake System	Good
Dashboard	Good
Interior	Good
Safety	Good
Seat/Carpet	Good
Test Drive	Good



Report

Exterior		GOOD SCRATCHES DENTS CHIPS RUST DENTS TOUCH-UPS							Details
		OK	S	D	CP	R	DT	TU	
1.	Front Bumper		X						
2.	Hood	X							
3.	Pass Front Fender	X							
4.	Pass Front Door	X							
5.	Pass Rear Door	X							
6.	Pass Rear Quarter	X							
7.	Rear Bumper		X						
8.	Trunk	X							
9.	Tailgate	X							
10.	Driver Rear Quarter	X							
11.	Driver Rear Door	X							
12.	Driver Front Door	X							
13.	Driver Front Fender	X							
14.	Front Grill	X							
15.	Overhead Rack	X							
16.	Front Spoiler	X							
17.	Wheel Well Flairs	X							
18.	Roof	X							
(S)Scratch (D)Dings (CP)Chip (R)Rust (DT)Dent (TU)Touch-up									

Exterior Overall Rating:

Good

		OKAY	CHIPS	SCRATCHES	CRACKED	
Glass		OK	CP	S	CR	Details
19.	Windshield	X				
20.	Pass Front	X				
21.	Pass Rear	X				
22.	Rear window	X				
23.	Cargo Light	X				
24.	Driver Rear	X				
25.	Driver Front	X				
26.	Fog Lights	X				
27.	Headlights	X				
28.	Front Turn Signals	X				
29.	Rear Turn Signals	X				
30	Tint	X				
(CP)Chip (S)Scratch (CR)Cracked						

Glass Overall Rating: Good

		OKAY	CHIPS	CRACKS	HAZYNES	MISSING	SCRATCHES	
Mirrors:		OK	CP	CR	H	M	S	Details
31.	Driver Side View	X						
32.	Pass Side View	X						
33.	Rear View	X						
(CP)Chips (CR)Crack (H)Hazy (M)Missing (S)Scratches								

Mirrors Overall Rating: Good

		EXCELLENT	GOOD	FAIR	POOR	
Tires and Wheels		E	G	F	P	Details
34.	Condition of Tires	X				
35.	Tire Tread	X				80%
36.	Wheel Make and Model	X				
37.	Wheel Size	X				
38.	Condition of Wheels	X				
39.	Spare Tire	X				
40.	Tire Changing Tools	X				
41.	Jack	X				
(E)Excellent (G)Good (F)Fair (P)Poor						

Tires & Wheels Overall Rating:

Good

Under Hood		NO	YES	Details
42.	Engine compartment Dirty	X		
43.	Oil leaks	X		
44.	Exhaust leaks	X		
45.	Exhaust smoke	X		
46.	Abnormal/Unusual noise	X		
47.	Transmission noise	X		
48.	Any non-stock modification	X		
49.	Belts Cracked	X		
50.	Fluid leaks	X		
51.	Hoses stiff/cracked or patched	X		
52.	Overheating Signs	X		
53.	Radiator Corroded/	X		
54.	Leaking Radiator	X		
55.	Battery corrosion	X		
56.	Oil Level - low	X		
57.	Power Steering Fluid Level - low	X		

58.	Brake Fluid Level - low	X		
59.	Transmission Fluid - dirty	X		
60.	Coolant level - low	X		
61.	Windshield Washer Fluid level - low	X		
(N)No (Y)Yes				

Underhood Overall Rating:

Good

Suspension:		PASS	FAIL	Details
62.	Ride Quality	X		
63.	Suspension Noise	X		
64.	Condition of Suspension	X		
(P)Pass (F)Fail				

Suspension Overall Rating:

Good

Electrical System:		WORKS BROKEN CRACKED			Details
		W	B	CR	
65.	Headlights	X			
66.	High Beams	X			
67.	Daytime Running Lights	X			
68.	Front Blinkers	X			
69.	Fog Lights	X			
70.	Tail Lights	X			
71.	Rear Blinkers	X			
72.	Brake Lights	X			
73.	Interior Overhead Lights	X			
74.	Visor Lights	X			
75.	Front Wipers	X			
76.	Rear Wipers	X			
77.	Windsheild Sprayer	X			
78.	Driver Power Windows	X			
79.	Pass Power Window	X			
80.	Rear Pass Power Window	X			
81.	Power Trunk	X			

82.	Convertible				
83.	Radio	X			
84.	CD Player	X			
85.	CD Changer	X			
86.	DVD Player	X			
87.	Navigation	X			
88.	Driver Power Seat	X			
89.	Front Passenger Power Seat	X			
90.	Rear Power Seats				
91.	Third Row Power Seats				
92.	Driver Manual Seat				
93.	Front Passenger Manual Seat				
94.	Rear Manual Seats				
95.	Third Row Manual Seats				
96.	Heated Seats	X			
97.	Cooled Seats				
98.	Keyless Entry	X			
(W)Works (B)Broken (CR)Cracked					

Electrical System Overall Rating:

Good

Brake System:		YES	NO	Details
99.	Brake Noise		X	
100.	Brake Grinding		X	
101.	Brake Vibration		X	
102.	Emergency Brake Operational	X		
(Y)Yes (N)No				

Brake Overall Rating:

Good

Dashboard:		PASS	FAIL	Details
103.	Check Engine Light	X		
104.	ABS Light	X		
105.	TPMS Light	X		
106.	TPMS Readings	X		
107.	Maintenance Req'd Light	X		
108.	Change Oil Indicator	X		
109.	Oil Pressure	X		
110.	Engine Temp	X		

111.	Parking Brake Light	X		
112.	Service Suspension Light	X		
113.	Service Airbags Light	X		
114.	Speedometer	X		
115.	Tachometer	X		
116.	Battery	X		
117.	Dash Pad	X		
(P)Pass (F)Fail				

Dashboard Overall Rating: **Good**

Interior:		OK	YES	NO	Details
118.	Wind Noise	X			
119.	Ratting Noises	X			
120.	Unusual Odors	X			
121.	Cleanliness	X			
122.	Cupholder Condition	X			
123.	Cigarette Lighter	X			
124.	Hood Release	X			
125.	Trunk Release	X			
(Y)Yes (N)No					

Interior Overall Rating: **Good**

Safety:		PASS	FAIL	Details
126.	Driver Seatbelt	X		
127.	Front Passenger Seatbelts	X		
128.	Rear Seatbelts	X		
129.	Third Row Seatbelts			
130.	Horn	X		
(P)Pass (F)Fail				

Safety Overall Rating: **Good**

Seats & Carpet:		PASS	BLEMISH	DIRTY	Details
131.	Driver Seat	X			
132.	Front Passenger Seat	X			
133.	Driver Rear	X			
134.	Middle Rear	X			

135.	Pass Rear	X			
136.	Third Row Seats				
137.	Driver Side Carpet	X			
138.	Front Passenger Carpet	X			
139.	Rear Carpet	X			
140.	Third Row Carpet				
141.	Trunk / Cargo Area	X			
142.	Driver Side Floormat	X			
143.	Front Passenger Floormat	X			
144.	Rear Floormat	X			
145.	Third Row Floormats				
146.	Cargo Area Mat				
(P)Pass (B)Blemish (D)Dirty					

Seats & Carpet Overall Rating:

Good

Test Drive		EXCELLENT GOOD FAIR POOR				Details
		E	G	F	P	
147.	Acceleration	X				
148.	Shifting	X				
149.	Alignment	X				
(E)Excellent (G)Good (F)Fair (P)Poor						

Test Drive Overall Rating:

Good

Overall Condition of Vehicle:		EXCELLENT GOOD FAIR POOR				Details
		E	G	F	P	
150.	Overall Condition	X				
(E)Excellent (G)Good (F)Fair (P)Poor						

Clients Main Concerns were:

Overall condition, looking for an excellent condition new car feel

Comments:

1. REAR AND FRONT BUMPERS HAS SMALL SCRATCHES.
2. RUNS AND RIDES LIKE NEW
3. .NO MECHANICAL OR ELECTRICAL PROBLEMS

Thanks for Choosing Texas First Auto Inspections!
































































 **actron®**

Quick Test Results

I/M Monitors
Since DTCs Cleared

Misfire Monitor	ok	
Fuel System Monitor	ok	↓
COMP Component	ok	↘

AutoScanner® Plus

Vehicle Inspection Results

Sec Air System	n/a †
A/C Refrig Mon	n/a
Oxygen Sens Mon	ok
Oxygen Sens Htr	ok
EGR/VVT Sys Mon	ok ↓

Read Codes

Read Codes



No codes found
Code Summary

Global

No codes

Scanner® Plus